Coffee table-Laser C





Assembly instructions

•		0		0
	۰		0	

Holes made for pivots

•	0	0	o	0
۰	٥	۰	o	۰

Holes made for screws

- Remove the legs from the package. 2.
- To the holes made in the tabletop, apply the holes 3. made in the leg and install the M6 screw into the pivot.
- Tighten with an allen wrench (included in the pac-4. kage).
- To strengthen the structure, you can additionally 5. screw in screws (10 pieces per leg)
- Turn the table over and it's ready 6.

- 1. For each set of legs we add a set assembly kit which includes:
 - 10 pivots (double-threaded nuts) 👗
 - 20 screws
 - 10 pieces of M6 screws
 - 1 allen wrench



Cleaning and maintenance

Clean the table legs with a damp cloth.

Do not use caustic agents, scouring agents, bleach, alcohols and others of unknown purpose.

Coffee table-Laser C



Assembly instructions



°	٥	٥	۰	٥
٥	٥	٥	٥	۰

Holes made for screws

- Remove the legs from the package. 2.
- To the holes made in the tabletop, apply the holes 3. made in the leg and install the M6 screw into the pivot.
- Tighten with an allen wrench (included in the pac-4. kage).
- To strengthen the structure, you can additionally 5. screw in screws (10 pieces per leg)
- Turn the table over and it's ready 6.

Cleaning and maintenance

Clean the table legs with a damp cloth. Do not use caustic agents, scouring agents, bleach, alcohols and others of unknown purpose.



- For each set of legs we add a set
- assembly kit which includes:
- 10 pivots (double-threaded nuts) 👗
- 20 screws
- 10 pieces of M6 screws
- 1 allen wrench

